








SAW
DAW
DAT




PRW
FRS




BDX



01





02





W



03a






S

03b









04



05

BDX




06

S6A 1140 mm


M8A 1400 mm

M8A 1400 mm


S6A 1140 mm




07/1




07/2




07/3




08/1




08/2




09



10






11a





11b

BDX




12




13a

W



14a




15a


3.

2.

1.



16a



17a


60-150 mm

30-60 mm


18a

13b


S




14b





15b



16b



17b



18b

